

FIG. 1

$$G(X) = X^{16} + X^{12} + X^5 + 1 = 0$$




FIG. 2

$$G(X) = X^{n+1} \dots X^2 + X + 1 = 0$$




FIG. 3A

FIG. 3B




FIG. 4